

CLASS II WELL TEST / INSPECTION REPORT

FORM UIC- 7

DEPARTMENT OF NATURAL RESOURCES
OFFICE OF CONSERVATION
INJECTION AND MINING DIVISION

Operator: EAGLE US 2 LLC Code: E208			
Address: BRINE FIELD SUPERINTENDENT P. O. BOX 1000 LAKE CHARLES, LA 70602-			
Contact: BRINE FIELD SUPERINTENDENT		Phone: 337-708-5717	
Date: 01/13/2023 Well Name: PPG 007B		Serial Num: 67270	
Field: SULPHUR MINES Code: 8759		Parish: CALCASIEU Code: 10	
Section: 029 Township: 09S Range: 10W			
Latitude (D/M/S): <u>30</u> <u>15</u> <u>12.930</u>		Longitude (D/M/S): <u>93</u> <u>24</u> <u>54.380</u>	

TEST/INSPECTION REASONS

50 INSPECTION-PERIODIC

50 INSPECTION- PERIODIC

PASSED

Permitted MASIP : 1165	Observed Tubing Pressure: 18	Well Status: Injecting
Well Sign Violation: No	MASIP Violation: No	Wellhead Condition: No
Leaking Salt Water Pump: No	Leaking Tank: No	Gauge Fittings: No
Leaking Flow Line: No	Excessive Vegetation: No	Unauthorized Injection: No
Containment Violation: No	Spill Outside Containment: No	Shut- In and Sealed: No
Other: No		

Comments: This is a Brine Mining Well
Operator was pumping 205gpm @ 18psi @ time of Inspection around 1pm.
Did sounding in Crystal Lake the large body of water North West of Cavern #007B.
Did most sounding along the edge of the grass along the bank, did do 2 short sounding in the middle of the Lake but the water depth was over 10' deeper than my measuring pole.
On the boat riding & sounding along the bank I observed NO bubbling or hydrocarbon smell @ that time.

N/A
Operator's Representative

WILLIAM CARNES
OC/MD CEA
Arrival Time:

Departure Time:

CLASS II WELL TEST /INSPECTION REPORT

FORM UIC- 7

DEPARTMENT OF NATURAL RESOURCES
OFFICE OF CONSERVATION
INJECTION AND MINING DIVISION



Subject: Crystal Lake

Photo File Name: 390342407579319933/Lake Cyrstal @ the Sulphur mines.jpg

CLASS II WELL TEST /INSPECTION REPORT

FORM UIC- 7

DEPARTMENT OF NATURAL RESOURCES
OFFICE OF CONSERVATION
INJECTION AND MINING DIVISION



Subject: Crystal Lake .. Sulphur mines

Photo File Name: 390342696533326432/Lake Cyrstal - Sulphur mine.jpg 3.jpg

CLASS II WELL TEST /INSPECTION REPORT

FORM UIC- 7

DEPARTMENT OF NATURAL RESOURCES
OFFICE OF CONSERVATION
INJECTION AND MINING DIVISION



Wind NNW 10 to 15 mph
approx 60° Temp.

West side looking East
towards Well #007B

Subject: Crystal Lake .. Sulphur mines

Photo File Name: 390342871247331703/Lake Cyrstal - Sulphur mine.jpg 2.jpg

CLASS II WELL TEST /INSPECTION REPORT

FORM UIC- 7

DEPARTMENT OF NATURAL RESOURCES
OFFICE OF CONSERVATION
INJECTION AND MINING DIVISION



Subject: Crystal Lake .. Sulphur mines

Photo File Name: 390343372325335969/Lake Cyrstal - Sulphur mine.jpg